

RJM Corporation  
Ten Roberts Lane  
Ridgefield, CT 06877  
203 438-6198

October 17, 1991



Mr. Aaron Nissen  
Results Supervisor  
Intermountain Power Service Corporation  
Rte. 1 Box 864  
Delta, UT 84624

Ref: B&W Comments Dated 9/24/91

Dear Aaron:

The following comments are referenced by the item numbers as contained in the 9/24/91 B&W comment letter:

- Item 1 B&W concurs with RJM Corporation that segmenting the back ring addresses the buckling problem currently experienced on the burners. However, B&W's recommended gap clearance tapering from 0" at the OD to 1/4" at the ID is much too small based on our finite element deformation analysis. This gap should be on the order of .75" for four segments and proportionally smaller for six segments.  
 $4 \times .75 = 3"$   
 $6 \times .5 = 3"$
- Item 2 We concur with B&W. The latest research reports on in-depth studies performed on similar burners in England show that coal volatility and swirl number are interdependent. This study recommends that outer zone swirl numbers should be between .5 and 1.0. Based on this latest research, RJM is recommending a swirl number in the outer zone of .91.
- Item 3 I believe after B&W discusses the recirculation parameter with their CFD experts, they will understand the recirculation trends predicted by RJM Corporation.
- Item 4 RJM must disagree strongly with B&W. Introducing swirl into an air balancing program introduces error by the amount of 1% for every 10° change in the vector direction of the air from an axial position. Air balancing must occur with the air doors in the 100% open position for accurate results and then the air doors properly set on all the burners to the same position. If this procedure is followed, there will be no unbalanced burners.
- Item 5 No comment.

Mr. Aaron Nissen  
October 17, 1991  
Page No. 2

- Item 6 As stated earlier, with the swirler in place flame scanning may be more difficult. The B&W concept of having the flame scanner upstream of the lighter when viewed from the rotation of the combustion air increases the difficulty of flame scanning. Adding an additional site window, such as will occur when the swirlers are installed, might add to scanning limitations. However, this question will be quickly answered after the swirlers are installed on Unit 2. A decision can be delayed as to whether or not a second scanner should be installed on Unit 1 until after Unit 2 comes back on line.

Additional comments with reference to the B&W drawings:

1. B&W does not provide any detail of the back plate assembly. RJM Corporation, therefore, cannot make any critical analysis until that detail has been received. IPSC should not approve B&W's design until these details have been received and reviewed carefully. Also, radial support bars for the throat sleeve assembly and outer zone register assembly must be included in B&W's design.
2. RJM Corporation has no objection to B&W utilizing six segments instead of four as proposed by RJM Corporation, provided the ID, OD and butt gaps are sufficiently large to permit growth of the plate.
3. The attached drawing shows RJM's recommended method of mounting the back plate using two supports. This keeps the plate properly centered in the back plate assembly, prevents cocking, and allows the plate to grow without binding. If B&W is just installing segmented plates between two channels as the drawings seem to indicate IPSC can expect problems when the plates cock and bind due to thermal growth. Some form of centering support is required.

If you have any questions or comments, please feel free to give me a call.

Very truly yours,

  
Richard J. Monro  
President

RJM/sv  
ipach&w.ltr  
Enclosure

RJM Corporation  
Ten Roberts Lane  
Ridgefield, CT 06877  
203 438-6198



**FACSIMILE TRANSMITTAL COVER SHEET**

DATE: 10/17/91 FAX NO.: \_\_\_\_\_

Please deliver the following pages to:

COMPANY: IPSC NAME: AARON NISSEN

REFERENCE: RJM COMMENTS ON BEW POSITION PAPER

THIS FAX IS FROM: RICHARD MANRO

Number of pages 3 (including cover sheet) transmitting from Xerox Telecopier  
7032 (telephone 203 431-8255)

MESSAGE:

---

---

---

---

---

---

---

If you do not receive all the pages, please call back as soon as possible. 203-438-6198.

IP7\_003954

Memo  
Gale to  
Bruce  
cc.  
also BWR notes  
KIM notes

Went BWR to ~~insert~~  
these recommendations

12-309  
12-314

Response to 10/15 meeting

BWR design approval on <sup>new</sup> burners

Conditional approval pending implementation of following  
recommendations (since no details) incorporate

Difficult to approve w/o design details on backplate assembly  
Conditional approval w/ these exceptions

Comments

Recommendation changes.

Backplate clearances  
slip cover  
radial supports

We want finalized details  
prior to  
final approval  
drawing for evaluation

Threat share meeting